



Mitja kocjančič &lt;veso266@gmail.com&gt;

---

## Sangean ATS909X2 problems

---

Mitja kocjančič &lt;veso266@gmail.com&gt;

12. september 2021 12:57

Za: service@sangean.eu

Hello there, in 23.06.2021 I bought your great Sangean ATS909X2 from Conrad

The radio was build someday in oktober 2020 (at least the sticker on the ANT-60 and the power supply says its 2020/10)

Its a great radio I can recieve many different MW/SW and FM stations with it, example: <https://youtu.be/S1npgqBek5l>

another example: <https://youtu.be/fdgfHF6-qSw>

3rd example: <https://youtu.be/PddHDMSs6MU>

but unfortunately it has some anoying problems

on SW and MW it generates some internal noise (some people say this is hand capaticence, because the noise on SW gets amplified when you place a hand over LCD)

Here you can see LCD QRM problem on SW: <https://youtu.be/qKl1hcWQt9I>

and here you can see the internal noise problem on MW: <https://youtu.be/RKG5TMLjK2A>

and when night falls and I want to listen to some station, the noise stays and it bothers me: <https://youtu.be/kbcpmApgMOg>

Now, I hope this issues can be addressed and fixed because apart from this issues your radio is the best World portable that exists right now

I will also be making videos about the noise after the radio is fixed (hope this will happen) to show the difference it makes before and after

Thanks for Anwsering and Best Regards